OPWC DISTRICT 4 INTEGRATING COMMITTEE 2022/2023 APPLICATION SUMMARY

SUBDIVISION:	Dayton	CONTACT PERSON:	Nick Dailey

PROJECT NAME: Findlay Street MRL-08 Outfall Improvements

	CRITERIA		RES	SPONSE		
	Project Type	Stormwater				
	General Project Summary	Replace a critical storm system failure. The existing outfall consists of an				
		84"concrete storm pipe discharging to the Mad River, 100 feet to the				
		west of N. Findlay Avenue. The concrete headwalls are spalling and				
		cracking, and much of the concrete channel has broken off and washed				
		away. The proposed project will rehabilitate the failing headwalls,		eadwalls,		
		channel and revetment.				
1.	Priority Project?	No				
2.	Total Project Cost	\$470,000				
	Funding Requested SCIP	\$200,000				
	Funding Requested LTIP	n/a				
	New/ Expansion	\$0				
3.	Type of Request	Grant	T			
4.	Local Match SCIP	\$270,000	57%			
	Local Match LTIP	n/a				
5.	Economic Health	5				
6.	Infrastructure Age	67 years				
7.	Generation of Revenue	None				
8.	Additional Funding	None				
9.	Readiness of Project	Ready to Proceed				
10.	Health & Safety - Category	Storm sewer				
	Response	The concrete portion	n of the outlet	t channel has ero	ded, le	aving only
		rebar visible. This structural failure is allowing water to wash out soil				
		from underneath the headwalls and causing the existing ground behind				
		the headwall to sink, and escape under the headwall and into the				
		channel. This creates a significant drop between the top of the headwall		of the headwall		
44	All Birink	and the ground.				
11.	Addresses District Needs	System Users		Avg. Daily Traffi		
		Acres Drained	277	Project in Multi Communities?	ple	No
		Percent of Community Served? Less than 25%				
12.	Economic development	None				
	# jobs being created					
	# jobs retained			-		
13.	Relieves Traffic Congestion Responds to Growth	n/a		LTIP only Criteria		
14.	Weighted Useful Life	40 years				
15.	Engineering as % of Construction	0%				
16.	Other Factors	See attached				
COM	MENTS					

27DaytonFindlaySummary 9/29/2022

1.0 Project Financial Information (All Costs Rounded to Nearest Dollar)

1.1 Project Estimated Costs

Engineering Services			
Preliminary / Final Design:	00.		
Construction Administration:			
Total Engineering Services:	a.)	00.	o %
Right of Way:	b.)	00.)
Construction:	c.)	430,000 .00)
Permits, Advertising, Legal:	e.)	00.)
Construction Contingencies:	f.)	40,000 .00)
Total Estimated Costs:	g.)	470,000 .00)
1.2 Project Financial Resources			
Local Resources			
Local In-Kind or Force Account:	a.)	.00)
Local Revenues:	b.)	270,000 .00)
Other Public Revenues:			
Local / ODOT - Let:	_ d.)	.00.)
ODOT PID:	_		
OEPA / OWDA:	e.)	.00)
CDBG:	f.)	.00)
Other:	_ g.)	0.00)
Subtotal Local Resources:	i.)	270,000 .00	57.4 %
OPWC Funds (Check all requested and enter Amount)			
Grant: 100 % of OPWC Funds	j.)	200,000 .00)
Loan: 0 % of OPWC Funds	k.)	.00.	
Loan Assistance / Credit Enhancement:	l.)	.00)
Subtotal OPWC Funds:	m.)	00,000	42.6 %
Total Financial Resources:	n.)	470,000 .00	

Form OPWC0001 Rev. 12.15 Page 2 of 6


OHIO PUBLIC WORKS COMMISSION DISTRICT 4

Round 2022-2023 Supplemental Questionnaire

Applicant:	City of Dayton
Project Title:	Findlay Street MRL-08 Outfall Improvements
pplication S	Summary:
Briefly describe	the project:
torm pipe dischapalling and crac	eded to replace a critical storm system failure. The existing outfall consists of an 84 inch concrete arging to the Mad River, 100 feet to the west of N. Findlay Avenue. The concrete headwalls are king, and much of the concrete channel has broken off and washed away. The proposed project will ailing headwalls, channel and revetment.

Other Factors

What other factors exist that make this project more important than other like projects?
The City of Dayton has very limited funds for storm water improvements. This is a critically needed rehabilitation project, that needs to be constructed as soon as possible. There are safety concerns due to the sinking of the ground behind the headwalls, as well as structural concerns.
Cracking and spalling of the concrete headwall indicates a need for replacement. Proximity to the Mad River Bike trail is a safety concern. Collapse of the structure could also mean collapse of a portion of the bike trail.



Disclaimer: Map and parcel data are believed to be accurate, but accuracy is not guaranteed. This is not a legal document and should not be substituted for a title search, appraisal, survey, or for zoning verification.